

TiO Software Suite Release Notes

September 18, 2017

Element Software Version Numbers

Software Suite Version: 4.3.1

Includes:

MC2 Version:	4.35
Audio Version:	5.30
Lighting Version	2.51
Android App Version:	4.3.1
iOS App Version	4.2.3

To see the current software versions of the Elements in your system, access the “Manage Your Elements” page from the Main Settings page in the TiO Pro app. All Elements will be listed and the version for each is shown.

Summary: TiO 4.3.1 is a mid-level software update that includes updates to the iOS app, Android App, and Lighting. This software update fixes some minor bugs along with improve remote access sign up process.

How to get the update: All TiO Home application updates are obtained by downloading the new version of the app from the Google Play Store or the Apple Store.

New Features and Improvements in Software Suite 4.3.1

1. **TiOConnect** product interface additions
 - a. none
2. **Audio** System Changes/Improvements
 - a. none
3. **Master Coordinator** Changes/Improvements
 - a. none
4. **Lighting** Changes/Improvements
 - a. Gen 2 TL4 backlight scheme matches the Gen 1 TL4 backlight scheme
 - b. Various bug fixes

5. **TiO Android App** (Phones/Tablets with Android 5 and up) Changes/Improvements
 - a. Remote Access authorization and login improvements
 - b. Easier access to manage elements
 - c. Security interface color changed to red when armed
 - d. Certain bug/crash fixes

6. **TiO iOS App** (iPhones, iPads)
 - a. Remote Access authorization and login improvements
 - b. Easier access to manage elements
 - c. Security interface color changed to red when armed
 - d. Certain bug/crash fixes

Please visit our new video based training at www.tiotraining.com

Known Issues in Software Suite 4.3.1

Android

- Certain brands of cameras cannot be configured and/or viewed in the Android app. Please contact tech support for list of known working cameras.
- Rapid volume change of follower SS1 may cause change in master SS1 volume.

iOS

- App will not load properly if WiFi calling is enabled.

MC2

- NEST accounts with multiple residences configured may only discover one residence's NESTs

Lighting (TL4/MTL4/TLLMP)

- No known issues.

SS1

- When capturing mood on certain music services, mood may only capture the first track in the list and not the currently playing track.
- Controlling volume of master SS1 in a StreamShare will also adjust volume of followers. Changing volume of follower will still only modify follower's volume.
- Output volume may be lower than expected on certain music services

TCWIFI/TCIP

- No Known Issues