

## TiO Software Suite Release Notes

July 31, 2017

### Element Software Version Numbers

---

**Software Suite Version: 4.3.0**

Includes:

MC2 Version:	4.35
Audio Version:	5.30
Lighting Version	2.50
Android App Version:	4.3.0
iOS App Version	4.22

To see the current software versions of the Elements in your system, access the “Manage Your Elements” page from the Main Settings page in the TiO Pro app. All Elements will be listed and the version for each is shown.

Summary: TiO 4.3.0 is a mid-level software update that includes updates to MC2, iOS app, Android App, Lighting, and SS1. This software update fixes some minor bugs along with adding Google Chromecast Built-In, expanded Camera support, and improved lighting performance and stability.

How to get the update: All TiO Home application updates are obtained by downloading the new version of the app from the Google Play Store or the Apple Store.

### New Features and Improvements in Software Suite 4.3.0

---

1. **TiOConnect** product interface additions
  - a. none
2. **Audio** System Changes/Improvements
  - a. Added support for Google Chromecast Built-In\*\*
  - b. Various bug fixes
3. **Master Coordinator** Changes/Improvements
  - a. Fixed intermittent issue where time zone was not set properly

**\*\*NOTE: After the SS1s have updated (maybe take up to 1 hour depending upon internet connection speed), Google ChromeCast Built-in may not be available for up to 72 hours due to Google server activation requirements. SS1s may also require power cycling after being activated on Google’s servers. Please contact tech support for any questions or issues regarding Google ChromeCast Built-in activation\*\***

4. **Lighting** Changes/Improvements
  - a. Improvements to connection and pairing performance, significantly reduced time to connect
  - b. Improved reconnection reliability
  - c. Light state will now return to previous state after power loss or update
  - d. Various bug fixes
  
5. **TiO-Pro Android App** (Phones/Tablets with Android 5 and up) Changes/Improvements
  - a. Add support for Google Chromecast Built-In\*\*
  - b. Expanded ONVIF camera support
  - c. Simplified cameras view page
  - d. Removed legacy update button
  - e. Fixed error message for RA signup with invalid username
  - f. Various music bug and crash fixes
  - g. Various bug/crash fixes
  
6. **TiO iOS App** (iPhones, iPads)
  - a. Various bug/crash fixes

*Please visit our new video based training at [www.tiotraining.com](http://www.tiotraining.com)*

## Known Issues in Software Suite 4.3.0

---

### Android

- Certain brands of cameras cannot be configure and/or viewed in the Android app. Please contact tech support for list of known working cameras.
- Rapid volume change of follower SS1 may cause change in master SS1 volume.

### iOS

- App will not load properly if WiFi calling is enabled.

### MC2

- NEST accounts with multiple residences configured may only discover one residence's NESTs

### Lighting (TL4/MTL4/TLLMP)

- No known issues.

### SS1

- When capturing mood on certain music services, mood may only capture the first track in the list and not the currently playing track.
- Controlling volume of master SS1 in a StreamShare will also adjust volume of followers. Changing volume of follower will still only modify follower's volume.
- Output volume may be lower than expected on certain music services

### TCWIFI/TCIP

- No Known Issues