

TiO Software Suite Release Notes

January 30, 2018

Element Software Version Numbers

Software Suite Version: **4.3.3**

Includes:

| | |
|-------------------------------|-------|
| MC2 Version: | 4.35 |
| Audio Version: | 5.36 |
| Lighting Version | 2.51 |
| Android App Version: | 4.3.3 |
| Android Music Standalone App: | 1.0.0 |
| iOS App Version | 5.0.0 |
| iOS Music Standalone App: | 1.0 |

To see the current software versions of the Elements in your system, access the "Manage Your Elements" page from the Main Settings page. All Elements will be listed and the version for each is shown.

Summary: TiO 4.3.3 is a mid-level software update that includes updates to the iOS app, Android App, and add new standalone music apps for iOS and Android. This software update fixes some minor bugs.

How to get the update: All TiO Home application updates are obtained by downloading the new version of the app from the Google Play Store or the Apple Store.

New Features and Improvements in Software Suite 4.3.3

1. **TiOConnect** product interface additions
 - a. none
2. **Audio** System Changes/Improvements
 - a. Firmware update
3. **Master Coordinator** Changes/Improvements
 - a. none
4. **Lighting** Changes/Improvements
 - a. none

5. **TiO Android App** (Phones/Tablets with Android 5 and up) Changes/Improvements
 - a. Updated Music Settings
 - b. Certain bug/crash fixes

6. **New Android Music Standalone App**
 - a. New music standalone app implementation

7. **TiO iOS App** (iPhones, iPads)
 - a. New Music page implementation
 - b. Certain bug/crash fixes

8. **New iOS Music Standalone App**
 - a. New music standalone app implementation

****NOTE****

1. After the SS1s have updated (might take up to 1 hour depending upon internet connection speed), Google Chromecast Built-in may not be available for up to 72 hours due to Google server activation requirements. SS1s may also require power cycling after being activated on Google's servers. Please contact tech support for any questions or issues regarding Google Chromecast Built-in activation.
2. Please be advised that the LED on the front of the SS1 will be turned OFF after the firmware update and will continue to remain that way.
3. Please ensure to restart the app on initial configuration of an SS1 with a MC system.

Please visit our new video based training at www.tiotraining.com

Known Issues in Software Suite 4.3.3

Android App

- Certain brands of cameras cannot be configured and/or viewed in the app. Please contact tech support for list of known working cameras.

iOS App

- Certain brands of cameras cannot be configured and/or viewed in the app. Please contact tech support for list of known working cameras and iOS devices that support their discovery.
- App will not load properly if WIFI calling is enabled.

MC2

- NEST accounts with multiple residences configured may only discover one residence's NESTs

Lighting (TL4/MTL4/TLLMP)

- No known issues.

SS1

- When capturing mood on certain music services, mood may only capture the first track in the list and not the currently playing track.

AZTS7

- Certain Music settings will no longer be functional with the firmware update. Please contact tech support for more details.

TCWIFI/TCIP

- No Known Issues

****NOTE: iOS older than version 10 will no longer be supported starting September 2018****