

TiO Software Suite Release Notes

September 26, 2018

Element Software Version Numbers

Software Suite Version: 4.4.0

Includes:

MC2 Version:	4.61
Audio Version:	5.36
Lighting Version:	2.51
TL4 Gen3 Version:	1.00
Android App Version:	4.4.0
Android Music Standalone App:	1.0.0
iOS App Version	5.2.1
iOS Music Standalone App:	1.0

To see the current software versions of the Elements in your system, access the “Manage Your Elements” page from the Main Settings page. All Elements will be listed and the version for each is shown.

Summary: TiO 4.4.0 is a mid-level software update that includes updates to the Master Coordinator, iOS app and Android app for Google Assistant voice integration with an addition of a new TL4 Generation3 Lighting Version for its pairing and configuration with the TiO system.

How to get the updates: All TiO Home application updates are obtained by downloading the new version of the app from the Google Play Store or the Apple Store.

All TiO Home system updates are obtained by clicking on the Check for Updates Now option on the System Settings page upon loading the Android or iOS application and applying the update.

Once the updates are obtained, you should be all set to pair and configure your installed TL4 Gen3 switches.

For using Google assistant voice integration, Link your TiO Home account with the TiO Home action on your Google Assistant app after authorizing Remote Access on the TiO Home app.

New Features and Improvements in Software Suite 4.4.0

1. **TiOConnect** product interface additions
 - a. none
2. **Audio** System Changes/Improvements
 - a. none

3. **Master Coordinator** Changes/Improvements
 - a. Firmware update to include Google Assistant
4. **Lighting** Changes/Improvements
 - a. Firmware update for the addition of the new product TL4 generation 3
5. **TiO Android App** (Phones/Tablets with Android 5 and up) Changes/Improvements
 - a. Onetime notification for voice integrations on app install/update
 - b. User notification for voice integration after Remote Access signup
 - c. Warranty card link on System Settings page
 - d. TL4 Generation3 pairing and configuration with ability to toggle between Dimmer and Switch mode on the Manage Elements page
6. **TiO iOS App** (iPhones, iPads)
 - a. Onetime notification for voice integrations on app install/update
 - b. User notification for voice integration after Remote Access signup
 - c. Warranty card link on System Settings page
 - d. App rater
 - e. Certain crash fixes
 - f. TL4 Generation3 pairing and configuration with ability to toggle between Dimmer and Switch mode on the Manage Elements page

****NOTE****

1. After the SS1s have updated (might take up to 1 hour depending upon internet connection speed), Google Chromecast Built-in may not be available for up to 72 hours due to Google server activation requirements. SS1s may also require power cycling after being activated on Google's servers. Please contact tech support for any questions or issues regarding Google Chromecast Built-in activation.
2. Please be advised that the LED on the front of the SS1 will be turned OFF after the firmware update and will continue to remain that way.
3. Please ensure to restart the app on initial configuration of an SS1 on a full TiO system.

Please visit our new video based training at www.tiotraining.com

Known Issues in Software Suite 4.3.5

Android App

- Certain brands of cameras cannot be configured and/or viewed in the app. Please contact tech support for list of known working cameras.

iOS App

- Does not support camera configuration edits.
- App will not load properly if WIFI calling is enabled.

MC2

- NEST accounts with multiple residences configured may only discover one residence's NESTs

Lighting (TL4/MTL4/TLLMP)

- No known issues.

SS1

- When capturing mood on certain music services, mood may only capture the first track in the list and not the currently playing track.

AZTS7

- Certain Music settings are not functional. Please contact tech support for more details.

TCWIFI/TCIP

- No Known Issues

****NOTE: iOS older than version 10 will no longer be supported starting September 2018****